

TONNAGE FOR FEES... 2511.05

2nd Number 22644

(Where necessary to be entered in Reg. Book.)
Residence

F.E.

Received by Chief Surveyor 24 OCT. 1896

Received from Chief Surveyor

VESSEL'S NAME *St. S. S. "Savan"* Report *Rec.* No. 33961

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	<i>2/20</i>	<i>Proportions</i>
Description of Framing:— <i>Deep framing</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **+ 100 A1 ("Steel") "Spar Deck"**, as recommended.

+ 100 A1 ("Steel")
"Spar Deck"

1 DR (Stt) & Spar DR (Stt) & Deep framing.

M. B. = Cell DB a 98' u E & B 42' f 126' 5875 APT 106.

FK. Cem.

C. K. J.
24/10/96



© 2021
Lloyd's Register
Foundation

6000-0096
22644

No. of Side Stringers					
WEB FRAMES, In E. & B. Space, No. & spacing	<i>One</i>	<i>One</i>			
BULKHEADS	Number.				
STIFFENERS					