


J. J. Monarch

Nwc 38926

It is submitted that before dealing with this case the Surveyors should be requested to state whether the sea ~~connections~~ cocks & valves & their fastenings have been examined, also the bilge suction arrangements of cocks pipes etc.


15/9/99
See. No Nwc 15-g-99



© 2021

Lloyd's Register
Foundation

NWC872-0004