

#1625

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at Topsam Date Feb 4 1857
on the Buganum Marsala Master Rich^d Perian
Tonnage 178 Built at P. Island When built 1856
By whom built _____ Owners Holman & Sons
Port belonging to Exeter Destined Voyage Per Quench
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port _____ Classed _____

REPAIRS this present date

Put in 8 ¹/₂ St. Siple Standard Turns to Upper Deck Beams 6 ¹/₂ Hanging Turn Riders to Hold Beams a Pair of Lion Tansons Turns and a Pair of Pointers. Hair-pipes changed for larger ones

Mr. Holman informs me that she has recently been Caulked and Sheathed with ¹/₂ metal at Swansea

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of <u>3 B 1 P 1 K</u>
Sheerstrakes	Ceiling	Cables <u>180 ft</u>
Topsides	Rudder	Hawsers and Warps <u>45 ft 1/2 45 ft 1/2 45 ft 1/2 45 ft 1/2</u>
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, _____ Caulking of Bottom, Deck, & Waterways. April 1857

This vessel is now in my opinion entitled to be Classed Y A as recommended by Mr. Gacher

The Amount of Fee.....£ : : is received by me,
Special..... : :
Certificate (if required) : :

Committee's Minute 1st May 1857

Character assigned 7/12