

REPORT of SURVEY for REPAIRS.

No. 607 Survey held at St. Mary's Date Jan 10 1859
 on the Brig Isabella Master Henry Battelle
 Tonnage 215 0 0 Built at P. L. Island When built 1857
 By whom built _____ Owners W. P. Ridway
 Port belonging to St. Peter Destined Voyage South America
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. Oct 1857 Port _____ Classed _____

REPAIRS

New Hammock

Survey for Stores

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3 Brown 1 Steel</u>
Sheerstrakes	Ceiling	Cables <u>2 heavy</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>1 lb</u> When put on <u>1857</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

The vessel's stores are good and
affluent, in examining her stores I found the
hammock cotton which is now replaced
John Holman

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required) : 2 : 6

Committee's Minute 25th January 1859

Character assigned 7 A





© 2021

Lloyd's Register
Foundation



Mr B. Seymour Esq
Lloyd's Register Office
London



© 2021

Lloyd's Register
Foundation