

Completion of Lucia Survey

1137

13159

REPORT of SURVEY for REPAIRS.

No. 13159 Survey held at Lumpur Date March 26 1855
 on the Ship Montmorency Master J. H. Hiddell
 Tonnage 812 ⁴²⁹⁴ ₃₅₀₀ Built at Luebe When built 1854
 By whom built J. C. Lea Owners J. Barnes & Co.
 Port belonging to Lumpur Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock in 95 gr

Survey, No. _____ Port _____ Classed _____

Has been placed in the graving dock & had set to the Deck beams
 5 pair iron hanging knees & pair of iron knees or joints over the transoms
 2 beams aft & forward now can be put to advantage to hold beams she has
 5 pair of iron hanging knees 2 pair of which are ^{extending so as to receive the bolts} long to beam aft now can
 be applied to advantage 1 iron crutch has also been set in aft the walls
 have been wood sheathed on both & fastened with yellow metal nails
 4 pair of chain have now been supplied #20 of which are new 30 of old but good

Condition of the

Waterways	Treenails	Windlass and Capstan
Decks	Breasthooks and Stems	Pumps
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Plank sheers	Keelsons	Sails
Strakes	Clamps and Shelves	Anchors
Rides	Ceiling	Cables
Decks	Rudder	Hawsers and Warps
Deck (Bottom) and Counter	Copper	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways	

is now in an efficient condition for the safe conveyance
 of any perishable cargoes to & from all parts of the world & recommend
 her to be classed as before recommended 7A1

Amount of Fee.....£ 1 : : : is received by me,
 Special..... 5 : 5 : : 31/3/58

Certificate (if required) Given
 Committee's Minute 3rd April 1855
 Character assigned 7A1



Submitted to the Registrar

REPORT OF SURVEY FOR REPAIRS.

Montgomery
1889



© 2021
Lloyd's Register
Foundation