

"
'Ship Magnolia'"

all the requirements of
Rule Section 83 - (Surveys
1 & 2) has been complied
with. Air courses, timbers
& listings taken out and
the Timbers found good.
Windlass unhung found
good, the linings are new.
Kessel scraped bright from
Keel to deck - Bolts & ~~bricks~~
driven out generally very
good - a stroke next to waterway
taken out the beams are good &
timbers at buttocks very good.
Kessel has had a very
extensive repair & generally
overhauled.

C. R. B. Ke.



Lloyd's Register
Foundation