

Port of Rotterdam, 31 July 1875.
Office: Westervaren 20-6

The Secretary Lloyd's Register Office
London.

My dear Sir!

Herewith the certificate of the "Beach 4" in return: I can't accept it, for when you read my report you will find that the vessel is copperfastened (in accordance with 46 par. 1. and more on that). Mr. Cornish our Surveyor has seen that vessel, and I suppose he has taken notice in his book about the Copperfastening of that vessel.

I hope he will remember, as I told him that I had recommended to drive in four Copperthroughbolts through each outside plank; and as he saw how many additional Stanchbolts were driven in...

Also she is built under Special Survey for the distinctive Mark \times , and I have recommended her for eleven or twelve years; because I hope she should have 12 years, perhaps.

About the third Anchor are not tested; you must know that first third Anchor was a Porter Anchor of 24-3-16. fastenings 24 1/2 tons. 182006. One Walker March 3. 1875. w. sig. Robt. Burrell. that was in scene with Banca Ventus. — But I made objection about the weight; and then after much trouble they send on board an other Anchor of 27 1/2 cwt. without testing.

I remain Dear Sir

Your obedient Servant



3/17/5-
Re Cornish to-
Wharf R.M.



© 2018

Lloyd's Register
Foundation