

Surveyor 21. 8. 00

Received from Chief Surveyor

S.P. No. 104.

Report Rot. No. 2990

The Chief Surveyor are desired on this case for the consideration of the Classing Committee.

to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to state any exceptional features in connection with the case, so that the Classing Committee may have all the salient points before them. — Extract from Sub-Committee's Report, 24.5.92.

et entry.

It is submitted the Newcastle Surveyors be informed that the Rotterdam Surveyor reports that the engines & boilers will be fitted with Shields - and that all parts of the hull have been finished but that only a few plates in top of casing aft require to be riveted when the boiler is in place. They should therefore be requested to see that the work remaining to be done to complete the vessel be carried out to their satisfaction & report the particulars in usual manner with a view to the vessel's classification.

S. b. J. W. C.
21/8/00

S. J. 21/8/00

J. H. T.
21/8/00



© 2018

Lloyd's Register
Foundation