

Received by Chief Surveyor 27. 2. 99

Received from Chief Surveyor _____

VESSEL'S NAME La S.S. "Fremington" Report Sld. No. 19571

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Proportions</u>
Spar Sheerstrake . .	✓	✓
Description of Framing:— <u>Ordinary.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A 1 ("Steel") as recommended.

+ 100 A 1 ("Steel")

1 DR (Lm). "Well Deck".


W. B = DB + 65' 7 1/2 FPT 18 t

FK 3BH Cem. A & CP Mch. Aft.

C. H. J.
27/2/99

It should be pointed out to the Surveyor that the depth from top of floors to top of main deck beams as stated in his report is in error, and he should be requested to rectify this.

Rpt to Sld.
29/2/99.



© 2021
Lloyd's Register
Foundation