

PORT OF SUNDERLAND,

WED. 25 APR 1900

23rd-April, 1900.

PATRICK SALMON

Messrs J. Blumer & Co, examine the propeller  
and propeller shaft of the S.S. "MONTWOOD", <sup>1141</sup>/<sub>715</sub> tons  
(No. in Builders Yard 153) for the purpose of ascertaining  
and reporting the amount of damage alleged to have been  
sustained by the vessel striking the quay on the 2nd-April,  
1900.

On examination found propeller broken. Recommended  
tail end shaft to be tried in a lathe and new propeller  
fitted in lieu of defective one so as to put the machinery  
of the vessel in the same efficient condition as before the  
accident occurred.

*Patrick Salmon*

Fee £1-1-0.

Less 10% 2-0

Net £0-19-0.



© 2021

Lloyd's Register  
Foundation

SLD1022-0227

*Report not used  
Sunderland No 20070  
J.S. 12/4/00*