

Lloyd's Register of British & Foreign Shipping.  
Sunderland. Aug<sup>t</sup> 18<sup>th</sup> 1849

Aug

Charles Graham Esq<sup>r</sup>

Sir

In reply to your letter under date  
7<sup>th</sup> inst referring to the stepping of the frame  
timbers in the Barge "William Simpson"; in  
explanation I beg to say the statement in the  
report on that vessel is an error and should  
have been  $\frac{1}{3}$  as the frame is generally so worked  
throughout. I am sorry it should have arisen  
and trust this explanation will be satisfactory

Rem<sup>y</sup> Yours

Obat<sup>d</sup> Serv<sup>t</sup>

Thos. B. Stacey



© 2021

Lloyd's Register  
Foundation

SL0930-0037



Lloyd's Regis  
Foundation