

Top Timbers	"	9	"	7 1/2	5	Wales	4	Ceiling
SLD931-0125	"	9	"	7 1/2	5	Short Hoods	5	Ditto
	"		"				4	Hold
							2	

4708
Lloyd's Register of British & Foreign Shipping.
Sunderland, March 30th 1852

Charles Graham Esq
Sir

In pursuance of your letter of 24th inst the undersigned yesterday surveyed the new Barge belonging to Mr. W. Hay in dry dock, and we have to inform you that in the course of our examination we found the Peasroom knees, and part of the poop beams, had been fastened with iron bolts, but were then driven out and of metal substituted, we also found the after and foremast beams of the poop & forecabin, the upper and lower throat bolts in the iron standards in front of the Poop, of iron and the bolts in the cat tails of iron, and the bolts in the Hold Beam knees, and dead wood knee, too small.

Due notice in writing was immediately forwarded to Mr. Hay who has promised to remedy all the above imperfections, and when done we are of opinion she will be entitled to clap 13 A.S.

We remain Yours

Obd^t Servts

Thos. B. Selous

James Lawrence

Fastenings. — To Hold Beams

Deck Beams