

as per Section

- 2nd. On the plating during the process of riveting
3rd. When the beams were in and fastened, }
and before the decks were laid.... }

Dec. 4 11 14 18 22 / 83 Jan'y. 5 15 16 18 22 25 30 Feb'y. 16 21 14 15

SLD 946-0019

REPORT, No. *13148* FROM *Sunderland*

DATE *28/6/83*


ON THE *Triano*

REMARKS OF THE CHIEF SURVEYOR.

*It is submitted that this vessel appears worthy
the favorable consideration of the Committee
to be classed 100A 1 Spar Deck as recommended
one deck (iron) & spar deck.*

3 Iron Beams

*Provided a bulk plate is fitted
keelson as required by the Rules,
Case on the face of the report.*



© 2021

Lloyd's Register
Foundation

JMR

*to the side interest
which is not stated in the*

27/7/83