


J. P. Dunmail, W. Supt. Report No. 5400.

No. *1329*

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office,



TESTS OF BOILER STEEL.

Tests of *one* Steel plate manufactured by *Messrs H. Colville & Sons* of *Mosherwell* for Boiler No. *870* to be constructed by *Messrs Blair & Co* of *Strocton* for *S.S. No 145* building by *Messrs Austin & Sons*

Date first visit *26/9/83* last visit *26/9/83* No. of Visits *one*

The *plate* specified in the accompanying copy of Advice Notes were rolled from *one* charges. The tensile test has been applied to *the* samples as set forth below, and the temper and bending tests *proved satisfactory.*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.	%	
					Ins.	Ins.	Ins.	Tons.	Tons.		
<i>1</i>	<i>8.6 x 34 x 1/2</i>	<i>E476</i>	<i>1</i>	<i>3468</i>	<i>.492</i>	<i>1.548</i>	<i>.761</i>	<i>20.97</i>	<i>27.5</i>	<i>26.0</i>	<i>DP. 23/10/83</i>

Fee £ : :

Expenses £ : :

£ : :

To be paid by

The Manufacturers

Chas. Edwards

Surveyor, Lloyd's Register,

Glasgow 24/10/83



© 2021

Lloyd's Register Foundation