

Ayala Rd 13880

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

No. 2923.

(Received at London Office,



TESTS OF BOILER STEEL.

Tests of 7 Steel Plates manufactured by Messrs: J Colville & Sons of Motherwell for Boiler No. 337 to be constructed by The N. Eastern N.E. Co of Sunderland for

Date first visit _____ last visit _____ No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests as required by Circular No 438

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	19. 2 3/4 x 5 7/8 x 49/64	L600		994	.8	1.58	1.264	34.75	27.4	25.5	
2	12. 10 3/4 x 4 5/4 x 1/16	F144		96	.68	1.37	.931	25.36	27.2	31.0	

M 17/9/85

Fee £ 20 : :
 Expenses £ : :
 £ : :

To be paid by

© 2021
 George Harrison
 Surveyor, Lloyd's Register
 Glasgow
 15-9-85