

S.S. "Hampton" (Sunderland report No 14583)

No. 6319

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received at London Office)

TESTS OF BOILER STEEL.

Tests of 5 Steel Bars manufactured by Messrs J. Colville & Sons of Motherwell for Boiler No. 371 to be constructed by Messrs The North Eastern Navy Co. Sunderland for Messrs Blumer & Co. S.S. No. 90.



Date first visit January 18<sup>th</sup> 1888 last visit January 27<sup>th</sup> 1888 No. of visits

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a piece from one bar with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Stay Bar 2 3/4 Dia	G460		11	.69	2.03	1.400	36.77	26.2	25.0	

Handwritten initials: SF 1/2/88

Fee ..... £ : :

Expenses £ : :

£ : :

To be paid by



© 2021

H. M. Dove  
Surveyor, Lloyd's Register,  
Glasgow

25.1.88

SLD956-0323