


S.S. "Hampton" (Sunderland report No 14583)

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 6229

(Received at London Office,



TESTS OF BOILER STEEL.

Tests of 3 Steel Plates manufactured by Messrs D Colvill & Son of Motherwell for Boiler No. 371 to be constructed by Messrs The North Eastern Har. Ry Coy Sunderland for

Date first visit Dec 30th 1887 last visit Jan. 16th 1888 No. of visits

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn	Brlth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	6.1 Rad x 47 1/2 x 1	N227		8160	1.04	16 7/8	1.736	48.94	28.1	28.0	At 21. 1. 88

Fee £ : :
Expenses £ : :
£ : :

To be paid by

© 2021
H Done
Surveyor, Lloyd's Register
18.1.88