

TESTS OF BOILER STEEL.

Tests of 21 Steel ~~bars~~ manufactured by Messrs D Colville & Sons of Motherwell for Boiler No. 567 to be constructed by Messrs The North Eastern Marine Co Sunderland for Messrs J Blumer & Co S.S. No. 96

Date first visit February 4th 1888 last visit February 9th 1888 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests to pieces from 2 bars with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Stay Bars 2 1/2 dia L341			59	.52	1.72	.894	23.43	26.2	27.0	
2	" " " " "			62	.77	1.68	1.293	34.84	26.9	25.0	

Handwritten signature and date: H.P. 12/2/88

Fee £ : : :

Expenses £ : : :

£ : : :

To be paid by



© 2021

H. W. Stone
Surveyor, Lloyd's Register
Glasgow

Blowers 91
0567

Notes

Sreatm ^u



© 2021

Lloyd's Register
Foundation

REGISTRY OF COMPANIES

ROADS REGISTERED OF BULLOCK AND FOREIGN SHIPPING