

This vessel would appear to be
eligible to be classed 10A1, and
the class recommended is doubtless
an oversight of the extra years due
for being fastened with yellow
metal, per Section 46

13/5/73

© 2021

Lloyd's Register
Foundation

SOV895-0195