


No. 4933

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 23 Steel Bars manufactured by Messrs D Colville & Sons of Alto Thewell
 for Boiler No. 16 to be constructed by Messrs The Central Marine Eng Co. of Hartlepool
 for Messrs Wray & Co of St. N. 32 24 Rivets to be made by W. Galstone Eng Stockton
 Date first visit May 16 78 last visit May 17 78 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a piece from each bar with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Rivet-Bars 1/2 Dia 255			210	1-12	Dia .985	28-1	28.5	31.5		

W.P. 25/5/87

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

H. N. Dove
 Surveyor, Lloyd's Register
 Glasgow
 21.4.57