


No. 8950

(Received at London Office,



TESTS OF BOILER STEEL.

Tests of 6 Steel bars, manufactured by Messrs. N. Bannan & Co. of Parkhead for Boiler No. 868. to be constructed by Messrs. J. Richardson & Son of Hartlepool. for the S.S. No. 289 building by Messrs. R. Dixon & Co. Middlestree.

Date first visit 2nd Oct. last visit 6th Oct. No. of visits ^{Constant} attendance.

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to one samples as set forth below, and the temper and bending tests applied to piece cut off one bar with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
	Stay bars. 2 1/2 diam	K218		3	1.01 diam	.801	22.2	27.7	30.0		Ad

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

J. M. Johnston
 Secretary, Lloyd's Register,
 Glasgow 6/10/88.
 Lloyd's Register Foundation