

VESSEL'S NAME

Report Doc No. 34

F.E.

(“The endorsement is to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>Increased 1/2" & doubled</i>	<i>Proportions.</i>
Spar Sheerstrake . .		
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle). <i>Zed in excess of Rule requirements</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A. 1. (Steel) as recommended.

✠ 100 A. I. ("Steel")
3 Stks (See-o Teak S)

WB = bell D.B. a. 112', v. E. & B. 77', f. 152', 764 Z. F.P.T. 42 Z A.P.T. 20 Z
F.K. 6 B.H. C. em.

Q.S. E. J. M.
10/9/97

Lloyd's Register
Foundation

TRI1155-0011

"	"		
"	Quarter 'tween Dks.,	"	"
"	in Hold	"	"
WEB-FRAMES, In Fore Body, No.			
"		width & thickness	