

Surveyor 11.7.93

Received from Chief Surveyor

NAME Ltt. S.S. No. 90

Report Vdu No. 178

arks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24.5.92.)

First Entry

It is submitted that before this case receives the consideration of the Committee the Sunderland Surveyors should be requested to report, in a repair report form in the usual way, whether the openings over the engines and boiler have been efficiently covered.

J. H. C. M. J.
11/7/93

To Sd. 11/7/93



© 2018
Lloyd's Register
Foundation