

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

6th September, 1933.

Dear Sirs,

E.

I am in receipt of your letter of the 2nd instant respecting Messrs. Harland & Wolff's Yard Nos.1016/7, and in reply to your enquiry have to inform you that in the case of the engines for these vessels, where dowel pins are not fitted in the crankshafts, the yield point of the material for the crankwebs should be not less than 14 tons per sq. inch, as stated in your letter.

I am, Dear Sirs,

Yours faithfully,

Assistant Secretary.

The Surveyors,  
BELFAST.



© 2019

Lloyd's Register  
Foundation

W100-0297