

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as  
painted on Skin and now verified }

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME EMPIRE DEBEN

REPORT Sou.

No. 19649

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


This ship has a notation of "Examined L.R. 6.48" valid for 12 months assigned, subject to permanent repairs to bulkheads of O.F. tanks 5-12 at the Owners' convenience.

The SOUTHAMPTON Surveyors report (12.48) ship examined in dry dock and part recommended repairs carried out.

The ship was undocked pending decision on her future and has now sailed for Newport for breaking up (see also Mr. Jordan's memo. of 10.1.49).

IT IS SUBMITTED ACTION be DEFERRED pending confirmation of the breaking up of this ship.

28  
1  
49.



© 2020

Lloyd's Register  
Foundation

W1000-0206

the Tanks been tested?

Doubling Plates under Sounding Pipes

Salting

State if examined.

Sails

General Observations, Opinion as to Class, Recommendation, &c. :-