

SOUTHAMPTON 3925.

2353.

# Lloyd's Register of Shipping,

RECEIVED

27 JAN 1949

ANSD.....

31-32, Oxford Street,

Southampton, 26th January, 1949.

Dear Sir,

With reference to the Survey Reports, Southampton No. 19649, on the "EMPIRE DEBEN", which we are forwarding to you today, we have to inform you that we understand this vessel left Southampton for Newport about a week ago, and we have not received any official information from the Owners or Managers regarding the breaking up of this vessel, but understand from the local Ministry of Transport Office that vessel has proceeded to Newport for breaking up.

We are, Dear Sir,  
Yours faithfully,

J. Nicholas.  
pro The Surveyors.

The Secretary,  
LONDON.

ers \_\_\_\_\_  
Bottom Plating \_\_\_\_\_  
the Tanks been examined internally? \_\_\_\_\_

Have Ventilators and their Coamings been  
examined and found efficient? \_\_\_\_\_  
Air and Sounding Pipes \_\_\_\_\_

Frames or Frame at openings \_\_\_\_\_

" " at other places \_\_\_\_\_

Stringers, Clamps & Shelves \_\_\_\_\_

Selling \_\_\_\_\_

in clear

line of  
w said

4 of Pa

her Items :-

Copper, or Y  
(State if  
When fitted

Boats \_\_\_\_\_

Masts, Yards \_\_\_\_\_

Condition, h  
(State if

Equipment h

anchors, No

Cables (Stat

" length

" Rule

Chain Lock

Hawsers &

Standing an

© 2020  
Lloyd's Register  
Foundation  
W1000-0207



Referred to Mr. Perris.

Referred to Mr. Sperry

*Comp. H. R. Sperry*

*28  
1-1-19*

*28*

*45 Sa 22/10 Dtg BS  
12/48 Dtg BS*



© 2020

Lloyd's Register  
Foundation

PAIRS, OR EX  
How a  
Repair  
MARY OF DAMA  
Relieved ...  
Removed and F  
Fair or Repair  
RENT CONDITION  
ing of Decks  
ings  
s & Fastenings  
de Plating  
" in way  
es  
se Frames  
tudinals  
verses  
ons  
ers  
Bottom Plating  
the Tanks been  
the Tanks been