

REPAIRS, OR EXAMINATION AS PER RULE, FOR General Examination.

Vessel placed in Dry Dock. Bottom and rudder cleaned, examined and recoated.
The peaks machinery spaces

WOKINGHAM COPY

Enclosures

8th October, 1945.

S. Dear Sirs,

In compliance with your telephone call this morning I forward herewith the reports which have been received from Hamburg on the steamers "GENERAL SAN MARTIN" and "PRETORIA".

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,

NEWCASTLE-ON-TYNE.

Reverse Frames.....
Longitudinals.....

cient?.....
Have Sluice Valves been examined and found

Caulking.....
Treenails.....

Yes

W1000-0210

Lloyd's Register
Foundation

Copper
(S)
When
Boats
Masts,
Condit
(S)
Equip
Ancho
Cables