

respects satisfactory, and as the requirements of Table 31  
of the Rules are complied with, the weight of cable supplied  
will be approved by this Society.

3

s/s "Pearleaf"

It is submitted the Hartlepool Surveyors be informed  
that it is concluded that two spare bottom end  
connecting rod bolts have been placed on board, but  
as no mention of it is made in their report they  
should state whether this is so.



© 2020

13/4/17

Lloyd's Register  
Foundation  
W1001-0093

plied  
Society. The  
Surveyor should be informed accordingly