

n.7.43.

A further General Examination becomes due 10.46.
Action is deferred for dry docking after grounding.

11 JUL 1946

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME WINDING GULF

REPORT Bos No. 4097

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey Further grounding

When due.....

Subject to permanent repairs to stem and
stem plating etc. at the first convenient opportunity.

Action continue to be deferred for dry
docking after grounding.

JJ
11-7-46

CARGO BATTENS NOT FITTED

Plating to be drilled
at next S.S.



© 2020

Lloyd's Register
Foundation

W1002-0006