

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office \_\_\_\_\_ 19 \_\_\_\_\_

# Lloyd's Register of Shipping.

(Report on Vessel No. \_\_\_\_\_ Port \_\_\_\_\_)

## 870 SHIP FORGINGS OR CASTINGS

I have to report that the undermentioned ~~Iron or~~ Steel Forgings or Castings, manufactured by Pacific Coast Frg'g Co Seattle, W. for the Vessel No. \_\_\_\_\_, being built by Moore Shipbuilding Co of San Francisco, Cal. have been inspected by me as set forth below and found to be, so far as can be seen, \_\_\_\_\_

*Sound & free from defect*

*Asst*

*Seattle, W.*

ings or Castings.

870  
2-20

	STERN FRAME.	RUDDER <del>FRAME.</del>	STEM.
Inspection		<i>Steel ok.</i>	
Inspected		<i>Forged</i>	
		<i>as rep?</i>	
		<i>Proof</i>	
		<i>5-2-20</i>	
		<i>69840</i>	
		<i>21.5</i>	
		<i>180°</i>	
		<i>✓</i>	
		<i>✓</i>	

ETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.


(if any chargeable) *Charged*;

to be paid at \_\_\_\_\_

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

(if any chargeable) *Charged*;

to be paid at \_\_\_\_\_



© 2020

Lloyd's Register Foundation

Is Electric L...  
 s *three*  
 per rule *15.75*  
 fitted *17"*  
 ter end of the lin...  
 iner does not fi...  
 -corrosive *y*  
 gth of stern bus...  
 webs *30'2" x 10'8"*  
 Total surface...  
 rk *yes*  
 rk *yes*  
 ected to both Bil...  
*Fore peak,*  
 fitted in Engine r...  
 ine room bulkhead...  
*we*  
 above or below the...  
 a spigot and br...  
 yes  
 30  
 catch m...  
 No. of Certif...  
 o. and Descrip...  
 Are they fitte...  
 '0" Materia...  
 of riveting:  
 width of  
 hole in shell...  
 ial *stil*  
 No. of stre...  
 3/4 Top  
 Working  
 278  
 238 M...  
 Front plat...  
 g pressure  
 8 Mean  
 ps: Mater...  
 of stays in...  
 % of stre...  
 Diam.  
 H

