

1 - NOV 1945

to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME "SHENANDOAH" REPORT Sea. No. 3619

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~


In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Place of Survey... Docking. ~~When due~~

Subject to indented counter plating (s.s.) being dealt with at the Owners' convenience, to indented keel plates Nos.1 & 2 being dealt with at the first convenient opportunity, to permanent repairs to (worn) deck plating above (F & A) expansion bulkhead (p & s) being dealt with by 1.46.

NOTE:- Certificate for S.S. to be withheld pending renewal of worn plates as above.

WAB
31.10.45



© 2020

Lloyd's Register Foundation
11002-0216