

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report *October 24th 1940*

When handed in at Local Office

Port of *Balekha.*

No. in Reg. Book

Survey held at

*Balekha.*Date, First Survey *24. 10. 40*Last Survey *24. 10. 40*

19

16015. on the *Wood Iron or Steel**S.S. "HOMEFIELD"*

(No. of Visits)

TONNAGE:

GROSS *5324.*UNDER DEK *4822.*NET *3228.*Built at *Sunderland.*Owners *British India Steam Nav Co.*

Managers

By whom

S. Dwyer Esq. J.

Owners' Address

Port belonging to

*Glasgow.*When *1940*

MONTH

Surveyed *24. 10. 40* in Dry Dock? *11.*Name of Dock *London Dock.*

Destined Voyage

Cell/Dor/Dba

total capacity

feet; *uE&B*feet; *f*

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. *11051*Port *Cal*

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.

* for Special Survey.

Date of last Survey and of Periodical Surveys.

Machinery and Boiler

Surveys

(including date of N.B., if any).

*10011.**12. 39.**12. 38.**11. 39.**S.S. Pal. No. 3 12. 38.**C.L.**11. 38.**Cargo battens not fitted*

Society's Freeboard (if assigned) as painted on Ship and now verified

5' 11 3/4" ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition

Vessel in dry dock. Bottom made, cleaned, painted, & coated. Cables hauled. Due there. Ship docked in yard of N.S. Star's Ridge. 4 Shell-plates renewed. Seathen decks hauled. 15 Hatchways & 3 Tankways renewed. Windlass Steer gear hauled without opening up found in good order.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks <i>Good</i>	Bulkheads	Engine Room Skylights <i>Good</i>	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder <i>Good</i>	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now changed)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length (on board) mean diam.
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawser & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This vessel is in good condition & eligible in my opinion to remain as classed & to have fresh record of survey 10.40.

Survey Fee (per Section 20) *115/-*
 Special Damage or Repair Fee (if any) (per Sec. 20)
 Travelling Expenses (if chargeable)
 Second Surveyor's Fee (if any)

Fees applied for,

29-10-1940

Received by me,

19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

18 FEB 1941

Character Assigned

510 40

100H Subject
Cargo tanks not fitted
BS. 10.40/26



© 2020

Lloyd's Register Foundation

W1004-0027