

2. The width of the bearing surface of all hatch covers


DECK.  
ed ..... 502  
3 1/2'

ARD REPORT on the S.S. Homefield

NOTE. - The round of beam should be reported on the full breadth of vessel at the gunwale.

Particulars of alterations ~~is~~ given on back of verification form noted on report  
It is submitted the Certs. be forwarded to the Owners  
\* They be informed that under the Convention Freeboard Regulations the increase in maximum Summer Draught is  $3/4$  inch

It is further submitted the Calcutta Surveyors be advised of the action taken \* They be requested to forward full particulars of No. 3 hatchway on the Bridge Deck and the bunker and/or trimming hatches on the Bridge Deck and on the Upper Deck in the Bridge space, as this information is required in order that their report may be completed



22.8.32

© 2020

Lloyd's Register Foundation

D. MARK

Surveyor to Lloyd's Register, Calcutta.

The Surveyor should report the above to the

11  
10  
1  
14 1/2  
5 1/2  
- 9 1/2  
8

- 17 1/2  
6 1/4