

Tonnage { Gross 9142
 Net 5792
 Nominal 1001

Vessel built at Belfast By whom Workman, Clark & Co., Ltd.
 Engines made at -do- By whom -do-

COPY.

Lloyd's Register of Shipping



Port SAINT JOHN, N. B.,

JANUARY 29th, 1948.

This is to Certify that I have

part
 Surveyed the ~~Boiler~~ and Machinery of the twin screw steamer "PORT MELBOURNE" of London, 9142 tons gross, on January 9th, 1948 and subsequently whilst lying afloat at Saint John, N. B., for DAMAGE, if any, stated to have been caused when the tug "Ocean Hawk" collided with the vessel whilst moving from Berth No. 17 to Berth No. 9 at Saint John, N. B. on January 9th, 1948,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating ~~that~~ all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the ~~record~~ of machinery be retained as classed without fresh record of survey, subject to starboard propeller being specially examined at the next drydocking and dealt with as necessary (collision); also subject as previously recommended to one blade of port propeller being repaired. ~~be~~ made in the Register Book in the case of this vessel.

W. Neacie

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 10M-443 PRINTED IN U.S.A.

Special Damage or Repair Fee (if any) \$ 20.00
 (per Section 29.) W. & T. Rprs. 50.00
 Travelling expenses (if chargeable) \$ 4.10

Jan. 29 19 48
 Received by me,
 19

Lloyd's Register Foundation

W. Neacie
 Engineer Surveyor to Lloyd's

Owners' Address
 (if not already recorded in Register Book)
 3 - FEB 1948
 REPAIRS
 EXAMINATION
 ISLON
 I 1001
 Shelter Deck
 with freeboard
 7-12-47
 Examined 5, 17
 s.s. No. 2nd. N
 12,

of Register
 Voy
 of Classifi
 as in Regi
 CHARACTER
 Special Survey
 Date of Survey and of
 Special Surveys.
 of funnel(s)
 adjusted under
 adjusted under
 key Boilers?
 key Boilers?
 key Boilers?
 lance fitted at
 of it being effie
 ed at the after
 g efficiently lub
 of after bearing
 nd/or power fit
 ets of the
 e plate tow
 placed.
 he vessel w

Surveyors are request