

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

yes  
one

Do.

Donkey "

"

"

U.S. "PORT MELBOURNE" hwc. 84490.

S.S. No. 1 due 4.30. Survey held on machinery  
The reciprocating engines removed to Shops. overhauled  
& placed in order. All Shafting re-aligned  
Two new. L.P. Brown Wash. turbines have been fitted  
to work in conjunction with existing reciprocating  
engines & tested satisfactorily.

It is submitted that  
this vessel is eligible for  
THE RECORD. + L.M.C. 7.29.

To engine particulars in R.B. Add :-  
" 2 L.P. Turbines with D.R. gear and  
hydraulic Couplings "  
Amend N.H.P. to 1201.

J.R.M.

30. 7. 29

J.  
1/1

RE

LR

© 2019

Lloyd's Register  
Foundation

W1005-0034

ASIN

Survey Fee (per Section 25) £14: - : -

Special Repair Fee (if any) £10: 10: -

Fees applied for  
20 JUL 1929