

July 20, 1921.

November 1, 1921.

A. P. W. McNAB,

P. A. Becker, Esq., Lloyd's Agent, San Francisco, on the 25th July, 1921, survey the new steamer "BIRKENHEAD" recently launched by the Moore Shipbuilding Company of Oakland, California, and at present being completed at their wharf, for the purpose of ascertaining the amount of damage stated to have been caused by colliding with the new steamer "TUSTEN" when being moved from the Builder's wharf on 16th July, 1921.

On examination found:-

The after end of aftermost forecastle bulwark plate on starboard side of vessel heavily buckled and the rivetting of the upper deck stringer angle and half round sheer strake moulding in way of same started.

Recommended that the bulwark plates be part renewed and rivetting in the vicinity of damage be tested and all slack rivets renewed.

~~(Signed) A. P. W. McNab~~
Surveyor to Lloyd's Register.

Billed July 28, 1921.

Fee \$25.00



© 2021

Lloyd's Register
Foundation

W1006-0085

W1006-0086