

ENGINES &c — Description of Engines

S.S. **540** + **1125**

No. of Cylinders

November 2, 1921.

LH:HAB

Johnson & Higgins
433 California Street
San Francisco, California.

Gentlemen:

This will confirm our telephone conversation of October 24, 1921, notifying you of the damage to the Starboard Oil Pump, S.S. "BIRKENHEAD", Hull 166. This pump was manufactured by the National Transit Pump & Machine Company.

In testing out the pump and cargo lines, on October 14, 1921, a crack developed in the left hand oil cylinder wall, the crack extending around the circumference of the cylinder for about 10".

Necessary repairs will be made and in due course claim will be submitted under our Builder's Risk Policy.

Yours very truly,

(Signed) H. Levy
L.H.



© 2021

Lloyd's Register
Foundation

W1006-0087

Date of Test

Is a Safety Valve fitted to each Section of the Superheater which can be shut off from the Boiler

Diameter of Safety Valve

Pressure to which each is adjusted

Is Easing Gear fitted