

ast Report, No. 43908 Port N.Y.K.

periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and

F100A1 17-42-43.

S.S. N.Y.K. 103-12, 28

S.S. Bel. 102-37

## WOKINGHAM COPY.

By Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME

REPORT

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Committee

Dear Sir, 14th September, 1943.

With reference to the case of the steamer "ACME", I have to acquaint you that so long ago as June 1942, the Newport News Surveyors recommended that 90 fathoms of chain cable of Rule weight, size and test should be placed on board at an early convenient opportunity to replace that amount found worn and removed from the vessel.

Action was deferred for equipment by the New York Committee on the 12th August 1942. Subsequently in New York Report No. 43828 a notation of "Examined 4,43." was assigned subject to 30 fathoms of main cable being supplied at the first opportunity and to the remaining 60 fathoms being put on board at the end of the present emergency.

So far no report has since come to hand of any arrangements being made for the equipment to be brought up to the minimum war emergency requirements, and I shall be glad if you will take the matter with the Owners in an endeavour to arrange for this to be done at an early date.

Your reply on this point is awaited.

I am, Dear Sir,  
Yours faithfully,

Bennett, Esq.  
NEW YORK.

W1006-0154

Clerk to the  
Classification Committee

Lloyd's Register  
Foundation