

Jan. 1, 46.

4 E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "PANAMANTIAN"

REPORT

13 JAN 1947

Sng. No. 7272

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH


The class is subject to donkey boiler not being used and to No. 5 DE boiler not being used until repaired.

The vessel has since been under survey at Colombo (See Surveyor's Air Mail letter 16. 11. 46), and has proceeded to Hong Kong for repairs.

IT IS SUBMITTED action be deferred to await reports from Colombo and Hong Kong.

W1008-0008

18. 1. 47.



© 2019

Lloyd's Register
Foundation