

J.B.

st

HMV

30 SEP 1946

Chief Surveyors.....

Received from Chief Surveyors.....

VES NAME HAMPDEN REPORT N.Ns No. 5995

For the CHIEF SHIP SURVEYOR and CHIEF-ENGINEER-SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey..... DOCKING ; REPAIRS When due.....


Subject to indented shell plates etc.

(p & s.f) being dealt with at the first convenient opportunity.

8.46 N.Ns

23.9.46

CARGO BATTENS NOT FITTED



W1008-0128

© 2019

Lloyd's Register
Foundation