


total Heating Surface of Boilers 5838 $\frac{1}{2}$ Is Forced Draft fitted No. and Description of Boilers 2 Hull
 1000 $\frac{1}{2}$ 240 $\frac{1}{2}$ 36 10 13 No. of

of "Hampton".

Phil Rpt. No. 2091.

Before this case receives the consideration of the Committee the Philadelphia Surveyors should be requested to state whether the continuous liner is in one length as this is not clear from their report.



Handwritten signature and date: 9/2/14

© 2019

Handwritten signature: JRL

Lloyd's Register Foundation

W1008-0138

Thickness 4 Material of Lower back plate Steel Thickness 8 Greatest pitch of stays 4 $\frac{1}{2}$ 8
 Diameter of tubes $3\frac{1}{4}$ Pitch of tubes $4\frac{1}{2} \times 4\frac{1}{4}$ Material of tube plates Steel Thickness: Front $\frac{3}{4}$ Back $\frac{1}{5}$