

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates yes Are the Discharge Pipes above or below the water line below
Are they each fitted with a Discharge Valve always accessible on the platina of the vessel yes Are the Blow Off Cocks fitted with a spigot or not yes

Indo 8575

Submitted the Underwriters Surveyors be requested to forward the P^ro. R^{pt} Report on the boiler of this vessel.

SJC
6-8-14

Wm. S.

© 2020

Lloyd's Register
Foundation

Thickness _____ Range of tensile strength _____ Are the shell plates welded or flanged _____ Descrip. of _____
long. seams _____ Diameter of rivet holes in long. seams _____ Pitch of rivets _____ Lap of plates or _____
Percentage of strength of longitudinal joint _____ rivets _____ Working pressure of shell by rules _____ Size of manhole _____