

Report 8th May 1918. When handed in at Local Office

Spare Gear for the Machinery of Steel Twin Sc. 3 Mst. Sr.
"LIMA" of Stockholm, Burmeister & Wain's Yard No. 313.

Main Diesel engines with air compressors:-

One cylinder cover.

One cylinder liner.

3 crank pin top brasses with bolts and nuts.

4 crosshead bottom brasses with bolts and nuts.

1 pair of main bearing brasses of each size with bolts and nuts.

1 piston with rod and nut complete.

3 complete set of "Ramsbottom" piston packing rings.

12 exhaust valves with spindles, seats, chests, springs etc.

ready for insertion.

3 exhaust valves with spindles.

2 starting valves with chests, seats, springs &c. complete.

6 fuel valves with chests, seat, springs &c. complete.

3 fuel valve spindles.

6 bottom pieces for fuel valves.

1 guide pulley of each size used with bolts complete.

One complete set of all the working parts of the fuel pumps with
valves &c.

One complete set of springs of all sizes used for one engine.

3 thermometer-fasteners for cooling water discharge pipes from
exhaust valves.

One set of cylinder cover studs and nuts.


A quantity of assorted leather collars and packings.

2 valve spindles for the overflow valves.

One complete set of valves with seats and springs for one main
air compressor.

One set of piston packing rings for each piston for one main air
compressor.

One cooling coil for air compressor.



© 2019

Lloyd's Register
Foundation

W101-0073 (1/3)

One set of springs for one air compressor.

Auxiliary Diesel engines with air compressors:-

- 1 pair of crank pin brasses with bolts and nuts.
- 1 pair of crosshead brasses with bolts and nuts.
- 1 pair of main bearing brasses with bolts and nuts.
- 2 complete set of piston packing rings.
- 4 exhaust valves with seats, chests and springs complete.
- 2 exhaust valves.
- 2 fuel valves with seats complete.
- 2 fuel valve spindles.
- One spindle for the rotary valve.
- One complete set of springs for one engine.
- One set of valves for the fuel pump.
- 3 fuel pump pistons.
- One set of cylinder cover studs and nuts.
- One complete set of valves with seats for one air compressor.
- One high pressure cooling coil for air compressor.
- One set of piston packing rings of each size for one air compressor.

Auxiliary Machinery:-

- One complete set of valves for the auxiliary air compressor.
- One complete set of piston packing rings for do. do.
- One pair of crosshead brasses for the do. do.
- 2 crank pin top brasses for the do. do.
- 1 half set of valves with seats for the bilge pumps.
- 1 half set of valves with seats for the sanitary pumps.
- One set of wings with guides for the ballast pump.
- One spring for each size of escape valves.
- One valve spindle for each size of valves on the working and spare air receivers.

Donkey Boiler:-

- One safety valve spring.
- One feed check valve.



© 2019

Lloyd's Register
Foundation

W101-0073(2/3)

3.

set of valves for the boiler feed pump,
water gauge glasses.

ing:-

propeller shaft with nut.

two iron propellers.

set of coupling bolts and nuts.

ternbush complete.

set of Cedervall's lubricating box.

quantity of assorted bolts and nuts.

pieces of various sizes of iron, pipes, flanges, unions &c.

allowable for each.

various spare parts for the electric dynamos and motors and for

electric lighting and power installation.



A. J. J.

REGISTER OF SHIPPERS
REGISTER OF SHIPPERS



© 2019

Lloyd's Register
Foundation

W101-0073(3/3)