

10.23.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

112

111

VESSEL'S NAME *Stl S S VENDEMIARE*

Rpt. *Caen*

No. 110

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

18' Long

Transverse No. *496.88*

Depth "d"

Framing: Table No.

Description *Channel frame as approved*

Longitudinal No. *1490.65*

Proportions

Length =

13.57 F

Depth =

11.32 A

Deck Sheerstrake as approved.

The Anchors & Cables (with the exception of the stream anchor) have Bureau Veritas Certificates of Tests. (approved).

The *Caen* Surveyor reports the vessel placed in dry dock, the bottom cleaned & coated and some minor alterations carried out.

This vessel appears to have been built in accordance with the Revised

rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel)

1 dk (Stl) " Well dk "

Cell D.B. as v E 66' f 107' H05t, deep tanks aft 34' 205t, F.P.T. 77t, APT 22t.

F.K., H.B.H., Cem.

P 22 Q 87 B 50 F 23.

Date of build 10.25

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

The Surveyor should be informed that the notation ~~A.C.P.~~ is no longer provided for in the Rules.

The Surveyor should also be requested to forward the foregoing reports.

© 2020

Lloyd's Register Foundation

Dr 13/10/20

7.9.25.

Miss Dr. Blair
1310 1/2