

Did the Surveyor examine all the mountings of the Main Boilers? \_\_\_\_\_, and of the Donkey Boilers? \_\_\_\_\_

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? \_\_\_\_\_ Is an approved appliance fitted to the shaft to permit of it being eff

Has shaft now been changed? No If so, state reasons \_\_\_\_\_

the after  
iently lubric

s/s "Vendemiaire"

Caen 112.

d in g

This vessel was classed on the 13<sup>th</sup> inst & the record of + LMC 10. 25. was assigned.

It now appears that the distinguishing mark + was inadvertently recommended, as although the machinery was constructed under Special Survey the boilers were not.

It is submitted that the + be expunged from the record.

In Caen 20/11/25

*[Signature]*  
20/11/25

© 2020



Lloyd's Register  
W1011-0083  
Foundation

ster Book, co  
ample, B.S.

The machinery of this vessel as now seen is eligible in my opinion to be in the class contemplated (please see Havre Surveyors First Entry Report) without

THE SURVEYORS ARE REQUESTED NOT TO

If Stockists, state Mechanical Tests

tested and ent.

ed and