

26 SEP 1945

Yacht "AARLA"

Lis. 4090


Fal. 10313.

Lubricating oil pumps and pumping arrangement defective.

Temporary repairs effected at ^{6 ports} ~~six ports~~ to enable the vessel to proceed on voyage to U.K.

A further examination of the machinery has been made at Falmouth to enable the vessel to proceed to River Clyde.

It is submitted the vessel is eligible to remain as classed subject to the lubricating oil pumping arrangement being placed in satisfactory condition on vessel's arrival in River Clyde.



© 2020

Lloyd's Register
Foundation

25.9.45.

W1011-0208