

Port belonginy to

Chief Surveyors 1. 9. 03

Received from Chief Surveyors

'S NAME *Sec. Twin L. L. Yacht 'Hecate'* Report *EL.* No. *21109*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from *Suo-Committee's Report*, 24/5/92.)

Survey

First entry

When did

+100A1 ("Steel") in the yacht Register.
108.

BK 6 1/2" 4BH Cms. Lloyd AYCP P60' F30'

C. N. J.
1/9/03

© 2020

Lloyd's Register
Foundation

Diameter at smallest part 2.81" Area supported by each stay 289^{sq} Working pressure by rules 219 Material of Front plates at
Thickness 1 7/8" Material of Lower back plate steel Thickness 1/8 Greatest pitch of stays 13 1/2 Working pressure of pl
Diameters of bolts 3/4" dis cut 1 3/4" 1 1/4" 1 1/2" 1 3/4" 1 1/2" 1 3/4"