

other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

T.O. cloud '41 (W.E.)

5c.9.45.

nt to Chief Surveyors.....

Received from Chief Surveyors.....

ESSEL'S NAME "HOPESTAR" REPORT Liv. No. 126267

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.


In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

e of Survey. Damage When due.....

NOTED

Subject to permanent repairs to Shelter deck plating (p & s) abreast galley and fore end of No.4 hatch (p & s) and 'tween deck plating in way of deep tank (p & s) and Indented shell plating in way (p.s) at the first convenient opportunity.

For Mr Bryden to
note, re restoration of T.O.



W1013-0031

© 2020

Lloyd's Register
Foundation

Have the Tanks been tested? | Doubling Plates under Sounding Pipes | State if examined. | Sails.

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book this entry, thus for example:—"to remain as classed in the Register Book without fresh record of Survey." "to remain as classed and