

DNMS from 24/7/42
K 18/1/42.

Lloyds

to complete
examinations
pairs due to
Whenever the
of this form.

Cargo batter

ge ope

board (if as
Ship and no

by whom?

28 MAY 1942

ived by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SSEL'S NAME "HOPESTAR" REPORT L.A. No. 8284
L.A. 8285

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented shell plating (p.s) etc. being dealt with at the Owners' convenience, and to bulkhead between Nos. 1 & 2 holds being dealt with at the Owners' convenience.

The Lloyd's Agent HAIFA Surveyor reports (1241) an examination made of the vessel afloat after fire and no structural damage found except that the paintwork of the shell plating (p. & s) was scorched.

The Surveyor recommends this plating be cleaned, scraped and coated at the earliest opportunity.

Some damage to ropes and deck fittings also sustained and the Surveyor recommends these be made good at the first opportunity.

The vessel has now come under survey in dry dock at Newcastle.

It is submitted action be deferred pending receipt of the Newcastle Surveyors' report.

The Certificate of Classification to be endorsed "Cargo batters not fitted" and the same notation to be printed in the standard book.

penant attached.

W1013-0250 1/2

W1013-0249

openings

Inner Bottom Plating.....

Have the Tanks been examined internally?.....

Have the Tanks been tested?

examined and found efficient?

Air and Sounding Pipes.....

Ballast Pipes.....

" " at other places.....

Stringers, Clamps & Shelves.....

Salting.....

Other Items

Copper, or
(State
When fitted

Boats.....

Masts, Yards

Condition,
(State
Equipment

Anchors, L

Cables (Sta

" length

" Rul

Chain Loc

Hawsers &

Standing a