

For the information of Surveyors and the Committee only.

Received at                      Office,                      10

# Lloyd's Register of Shipping.

(Report on Machinery, No.                      Port                     )

No. 1139 XXXXXXXXXXXXXXXXXX  
**ENGINE FORGINGS OR CASTINGS.**

I have to report that the Forgings ~~or Castings~~ as herein described, manufactured

by Messrs. Walter Somers Ltd., of Halesowen

Order 4738/39

or the Engines No.                      being constructed by of The Parsons Marine

Steam Turbine Co., Ltd. for the Ship Max s.s. "HOPESTAR" for spares

, being built by                      of                     

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to

Newcastle.

~~gings~~

*A. Buchanan*

Birmingham. 19/2/40.

	CRANK SHAFT.	THRUST SHAFT.	INTERMEDIATE SHAFT.	TUBE SHAFT.
	1 Pinion Shaft			
	<del>WHEEL SHAFT.</del>			SCREW SHAFT.
	O.H. Steel			
	Forged			
	Yes			
Forgings	15 3/4" to 6 1/2"			
	1-14-2-14.			
Castings				
	Rough Machined.			
RESULTS.	281			
Weight	34.72			
sq. in.	19.8			
per cent	34.0			
inches	54.8			
Test	1800 W.F.			
Inspected	2/2/40. 14/2/40			

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:-

*Examined finished & found satisfactory - Stamped as above, and - H.C.F. 11.7.41.*


*A. G. Forster, Newcastle-on-Tyne*

Expenses 3. 0.

(any chargeable) £1. 6. 3.

To be paid at Birmingham. 11.7.41

wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.



W 1213 - 0270

TUE 1 APR 1941

Committee's Minute

Character Assigned

*Deferred*

rs of Classifi  
 ely as in Reg  
 RACTER.  
 eial Survey,  
 t Survey and of  
 onal Survey.  
 A 1  
 february  
 12. 39  
 board (if assi  
 Ship and now  
 whom? M  
 caused  
 d been  
 from  
 ide to s  
 nately s  
 No. 3 hdd  
 engine  
 and fr  
 on star  
 Items: -  
 enforce  
 detailed  
 Copper, or Y  
 (State if  
 When fitted,  
 Boats  
 Masts, Yard  
 Condition, h  
 (State if  
 Equipment  
 Anchors, No.  
 Cables (Sta  
 .. length  
 (or  
 .. Rule le  
 Chain Locker  
 Hawsers &  
 Standing and  
 Sails  
 sel in the Re  
 remain as cl  
 repairs  
 is four

The Surveyors are